Borden Company House, Allegany Mines AL-V-A-128 Green Row, Zihlman ca. 1850

The Borden Mining Company arrived in Allegany County during the mid-1840's and constructed housing for miners before opening the company's mines in 1850. This double or block house, located in the company's village of Allegany Mines, is a good example of the typical company house. It is a two story frame structure with weatherboarding and a four bays wide principal facade which includes two entrances. It rests on wooden posts and has a shed roofed kitchen addition on the northeast.

MARYLAND HISTORICAL TRUST

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME					
HISTORIC	Borden Company House,	Allogany Minos			
AND/OR COMMON	borden company nouse,	Arregally miles			
2 LOCATIO	N				
STREET & NUMBER	Green Row		Sixth		
CITY, TOWN	Zihlman vicinity of		CONGRESSIONAL DISTRICT		
STATE	Maryland		COUNTY Allegany		
3 CLASSIFIC	CATION	•			
CATEGORY DISTRICT BUILDING(S) STRUCTURE SITE OBJECT	OWNERSHIP PUBLIC PRIVATE BOTH PUBLIC ACQUISITION IN PROCESS BEING CONSIDERED	X STATUS —OCCUPIED —UNOCCUPIED —WORK IN PROGRESS ACCESSIBLE —YES: RESTRICTED —YES: UNRESTRICTED —NO	PRES _AGRICULTURE _COMMERCIAL _EDUCATIONAL _ENTERTAINMENT _GOVERNMENT _INDUSTRIAL _MILITARY	SENT USE _MUSEUM _PARK _PRIVATE RESIDENCERELIGIOUSSCIENTIFICTRANSPORTATIONOTHER:	
4 OWNER O	F PROPERTY				
NAME	Ethel L. Smith		Telephone #:	689-9768	
STREET & NUMBER	Route 2 Box 261				
CITY, TOWN	Frostburg	VICINITY OF	STATE, S Marvland 21532	zip code	
COURTHOUSE, REGISTRY OF DEEDS	N OF LEGAL DESCR	IPTION nty Courthouse	Liber #: 237 Folio #: 193		
STREET & NUMBER	30 Washingtor	Street			
CITY, TOWN	Cumberland		STATE Maryland	21502	
6 REPRESEN	NTATION IN EXIST	ING SURVEYS			
DATE		FEDERAL	STATECOUNTYLOCA	L	
DEPOSITORY FOR SURVEY RECORDS					
CITY, TOWN	<u> </u>		STATE		



__EXCELLENT

RL-1-K-123

CONDITION

__DETERIORATED

__GOOD __RUINS __UNEXPOSED

CHECK ONE

__UNALTERED

X CHECK ONE

__ORIGINAL SITE

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This building consists of a two story, four bays wide rectangular frame duplex structure with weatherboard siding. It rests on wooden posts with stones placed between them with no apparent water table. The gable front roof is covered with asphalt shingles. Eaves consist of a boxed cornice and soffit. Wall features include cornerboard. An original brick chimney on the interior has a corbeled cap.

Two replaced entrances are located in the center of the southwestern facade. One is of four panels and the other is of two panels and three lights. Slightly pedimented windows are pegged two over two lights with wooden lugsills. A wide porch on the southwest has a hipped porch roof supported by five square wooden posts. A frame addition on the northeast has a shed roof.

SPECIFIC DAT	ES ca. 1850	BUILDER/ARCH	HITECT	
1700-1799 X_1800-1899 1900-	ARTCOMMERCECOMMUNICATIONS	<pre>ENGINEERINGEXPLORATION/SETTLEMENTINDUSTRYINVENTION</pre>	MUSIC PHILOSOPHY POLITICS/GOVERNMENT	THEATERTRANSPORTATIONOTHER (SPECIFY)
PREHISTORIC 1400-1499 1500-1599 1600-1699	-ARCHEOLOGY-PREHISTORIC -ARCHEOLOGY-HISTORIC -AGRICULTURE XARCHITECTURE	COMMUNITY PLANNING CONSERVATION ECONOMICS EDUCATION	LANDSCAPE ARCHITECTURELAWLITERATUREMILITARY	RELIGIONSCIENCESCULPTURESOCIAL/HUMANITARIAN

STATEMENT OF SIGNIFICANCE

This duplex or "block" house is a good example of company housing rented to George's Creek coal miners. It is located on "Green Row" in the town of Allegany Mines, named for the Borden Coal Company's mine, but later remaned Zihlman. The houses on Green Row were all painted green. (1)

The Borden Company, which also operated a deep shaft mine in the town of Borden Shaft, built houses for their employees before they opened their mines in the early 1850's. (2) Katherine Harvey describes this company housing in The Best Dressed Miners:

The double house was typical of this region. These two family dwellings known as "blocks" were usually of frame construction, two stories high, providing three or four rooms and sometimes a shed kitchen for each occupant. (3)

Although most miners would have prefered owning their own homes there were advantages as well as disadvantages in the practice:

Families which occupied company houses were particularly vulnerable in times of strikes; on the other hand, the man who rented a company house might be the one retained in slack times. In 1875, when the Borden Company discharged ninety men, they were "those who do not occupy or board in the Company's houses." (4)

In 1951 the Borden Company sold the entire neighborhood to the Big Savage Refractories Company which quickly sold the houses to the tennants. (5) Many have been converted into single family dwellings as this one has.

(cont.)

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Allegany County Land Records
Schaft, John T. <u>History of Western Maryland</u>, Philadelphia: L.H. Everts Co. 1882
Harvey, Katherine A. <u>Best Dressed Miners: Life and Labor in the Maryland Coal Region</u>
1835-1910.Ithaca:Cornell University Press, 1969

CONTINUE	ON	SEPARATE	SHEET	ΙF	NECESSARY

CONTINUE ON	DEFENDATE DIEET TE MECEODAMI	
10 GEOGRAPH ACREAGE OF NOMIN	HICAL DATA NATED PROPERTY 50.45' x 150'	
VERRAL BOUND	ADV DECORIDEION	
VERBAL BOUND	ARY DESCRIPTION	
LIST ALL S	TATES AND COUNTIES FOR PROPERTIES OVERL	APPING STATE OR COUNTY BOUNDARIES
STATE	COUNTY	
STATE	COUNTY	
111 FORM PRE	PARED BY	
NAME / TITLE	David A. Dorsey, Historic Sites (Coordinator
	bayla A. borsey, miscoric sides	
ORGANIZATION		DATE
	Allegany County Historic Sites	August 29 1979
STREET & NUMBER	Arregary county historic sites	August 29, 1979 TELEPHONE
	2 Danahina Chuach	777-5944
CITY OR TOWN	3 Pershing Street	STATE
	Cumberland	Maryland 21502
	CUMPET LAND	11/41 1 1/41 10 10 10 10 10 10 10 10 10 10 10 10 10

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust

The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438

The building fits Ms. Harvey's description perfectly being a two story frame building with weatherboarding and a four bay front facade including two entrances. It rests on wooden posts and has a shed roofed kitchen addition on the northeast. In structurally sound and fair condition it represents a way of life and an economic system which has mostly disappeared.

Interview with owner, Ethel L. Smith, Zihlman, Md. December 1, 1978


John T. Scharf, History of Western Maryland (Philadelphia: L.H. Everts Co.) Vol. LL p. 1444

Katherine A. Harvey, Best Dressed Miners: Life and Labor in the Maryland Coal Region 1835-1910 (Ithaca: Cornell University Press) p.83

Ibid, p.89

Allegany County Land Records, Liber 235, Folio 715, and Liber 237, Folio 193

INVINTERY NO.	17 -1/- 1 122
DATE: Refind Gunes 7/6	AL-V-A-128
REMCDELING: Drastic, moderate, minor	
NAME OF PROPERTY: Renson Houses -	
LOCATION OF PROPERTY: Zihlman	
DIRECTION DWELLING FACES: SW ON GREEN KO	700.
NAME OF OWNER: MAP 3 ADDRESS: 0. 171 F. 30 Hace F. C.	A-128
FIRST STEVENS KT	Z Zinman Mazisza
295/4/6 Acreage - 25.68 x STORIES: 1() 2(3() 4() 5() 6() DWG 2()	150 689 3886
BAYS: 1() 2()	3() 4() 5() 6() 7() ()
3	
Dwelling Shape: (square, cross, rectangular)	
WALL CONSTRUCTION:	
(*) FRAME: Bevel, clapboard, weatherboard, wood shingles (*) BRICK: Bond type- common, English, Flemish. Sketch (*) STONE: Bond type- rubble, ashlar (random or regular) (*) Other: Coverings	o, board & batten (type?) variants. , quoins-plain, rusticated
WALL FEATURES: BELT COURSE, PILASTEES, OTHERS COMMENT FCUNDATIONS: HIGH, LOW, BRICK, STONE STONE Added WATER TABLE: NOW, PLAIN, BEVELED, MOULDED BRICK	really on comer part
WINDOWS, TRIM, SHUTTERS: 1/1() 2/2() 6/6() 9/6() 9/6() 9/6() pegged () nailed() wide () nar	lugsills stone
ENTRANCE, DCORS: LOCATION: HARDWARE: original() replaced() FAN LIGHT, TRANSOM, SIDE LIGHTS, PLAIN Paneled, Verticle, Horizontal Boards	1 2 panel 3 light
CCRNICE, BARGE, EAVES: (crown, fascia, soffit, bed) original() replaced() Rafter Ends, Modil	lions. Dentile Ent.
RCCF: [CABLE FRONT, GABLE FLANK, HIP, SHED, LANSARD, GAMBREL	, FLAT, DORMERS #
FORCHES: SHAPE OF ROOF - shed() hip(v) gable()	nal() replaced()
CHIMNEYS: MUMBER BRICK() STONE() CORBELED() ori LOCATION: Flush end() Inside end() Outside er	ad() Central() Intenion (A
ARCHES: Door and window: Keystone, Flat, Segmental, Semicir	cular
Significance - Cose to 100 415 old Date Constructed -	
Condition -	





wisn

AL-V-A-128

BORDEN COMPANY HOUSE, ALLEGANY MINES

7/29/79 - Paid Dovsey